


Catherine Hill Bay Jetty



The following slides show photos of several sections of the jetty from visual inspections completed in 2023 and 2025. These photos illustrate the condition of the jetty and the ongoing deterioration.

The sections of the jetty shown are Bent 1, 4, 12, 17, 20 and 26. The location of the bents are marked on the image above for reference.

2017



2023



2025



Bent 1

2023



2025



Bent 4

2023



2025



Bent 12

2017



2023



2025




Bent 17

2017



2023



2025



Bent 20

2017



2023



2025



Bent 26